

Dry Dock	Owner	Length (m)	Width (m)	Depth (m)	Ease of access	Availability for planned major refits	Suitability for emergency docking	Dockside infrastructure	Current site security	Personnel accomodation
Number 1 Dock, Rosyth	Babcock	310	31	10.8	Difficult	Good	Fair/Good	Extensive	High	Yes
Inchgreen Dry Dock	Cammell Laird	305	45	11.3	Excellent	Work needed	Adequate	Poor	Low	No
Belfast Dock	Harland & Wolff	335	50.3	12.2	Excellent	Good	Dependent on existing work	Good	Medium	No
Seaton Port, Teeside	Able UK	376	120	12.1	Excellent	Good	Dependent on existing work	Good	Low	No
Number 5 Dock, Birkenhead	Cammell Laird	289	42.7	11.5	Good	Good	Dependent on existing work	Good	Medium	No
Theoretical new Portsmouth facility	MoD	c310	c35	c12	Excellent	Would be Ideal	Would be Excellent	Extensive	High	Yes